## Listing of the Claims

Below is a listing of the claims with an indication of the status of each:

1. (Currently amended) A method for gluing microcomponents to a substrate in the production of microsystem components, comprising:

applying a reactive or nonreactive, pulverulent, hotmelt adhesive as a dispersion through a contoured screen with a result that said hotmelt adhesive is present only selected contact areas on a surface of at least one of a substrate and at least one microcomponent, said hotmelt adhesive not being present on other areas on said surface of said at least one of a substrate and at least one microcomponent, said at least one microcomponent being smaller than 1000µm, and granules of said reactive or nonreactive, pulverent, hotmelt adhesive having a diameter ranging from 0.5 to 150µm; and

applying the at least one microcomponent to the substrate by melting the hotmelt adhesive on the contact areas when the hotmelt adhesive is between the at least one microcomponent and the substrate, and bonding the at least one microcomponent to the substrate during cooling of the hotmelt adhesive below its melting point.

## 2-3. (Canceled)

4. (Previously presented) The method of claim 1 wherein melting the hotmelt adhesive during the step of applying the at least microcomponent to the substrate is achieved using a laser as a heat source.

## 5-13. (Canceled)

- 14. (Previously presented) The method of claim 1 further comprising a step of preheating of the surface to which hotmelt adhesive is to be applied.
- 15. (Previously presented) The method of claim 1 further comprising a step of afterheating the at

least one microcomponent after adhering to the substrate.

16. (Previously presented) The method of claim 15, wherein the afterheating takes place using a focused or global heat source.

17-18. (Canceled)

19. (Currently amended) The method of claim 1 wherein said step of applying the at least one microcomponent to the substrate step includes the steps of:

melting of said hotmelt adhesive at <u>said</u> selected <u>contact areas</u> bond sites on said surface by irradiating <u>said reactive or nonreactive</u>, <u>pulverant</u>, <u>hotmelt adhesive</u> a <u>powder layer</u> on the selected <u>contact areas</u> bond sites using a focusable heat source; and

removing the <u>reactive or nonreactive</u>, <u>pulverant</u>, <u>hotmelt adhesive</u> <del>powder layer</del> not incipiently melted.

20-21. (Canceled)